Oil Field Environmental Incident Summary

Responsible Party: Hess Tioga Gas Plant LLC
Well Operator: HESS TIOGA GAS PLANT LLC

Well Name: Myrtle Compressor Station

Field Name: N/A Well File #:

Date Incident: 8/29/2015 Time Incident: 14:00 Facility ID Number:

County: MOUNTRAIL Twp: 156 Rng: 94 Sec: 32 Qtr:

Location Description:

Submitted By: Alex Beach Received By:

Contact Person: Jason Henry

3015 16TH ST SW STE 20

MINOT, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building:0.8 MileDistance Nearest Water Well:0.8 Mile

Type of Incident Fire

Release Contained in Dike No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine

Other

Description of Other Released Contaminant:

Natural Gas Liquids. The amount of NGLs that were carried over through the flare has not been determined at this time.

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

Up until the time the fire was extinguished, there was the risk of exposure to excessive heat for the people and equipment in the immediate area.

Areal Extent:

The areal extent has not yet been determined.

Potential Environmental Impacts:

At this time the amount of area that the fire impacted has not been determined. There are no reasons to suspect any additional environmental impacts at this time.

Action Taken or Planned:

Portable extinguishers were used in attempts to knock down the fires. The local Fire Department was notified and did arrive on site to extinguish the fires. A fluid truck was dispatched to remove the liquids from the vessel to keep from carrying over to the flare. The defective components will be replaced.

Wastes Disposal Location: If there is any waste that needs to be disposed of as a result of this

incident, it will be taken to an approved waste disposal facility.

Agencies Involved: Local Fire Department

Updates

Date: 9/1/2015 Status: Reviewed; Followup Required Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Fire at compressor station. Due to lack of information and "unknowns" on report, followup is required.